


國立聯合大學第十宿舍




4樓 A417-4 書桌貼皮破損




2樓 A213-3 牆壁殘膠



6樓 A621-1 牆壁油漆剝落




6樓 A621-1 書桌貼皮破損



2樓 A209-3 床旁邊牆壁油漆剝落



3樓 A303-1 牆壁殘膠


 <p>A303-2</p>	 <p>A303-3</p>	 <p>A303-4</p>
<p>3樓 A303-2 牆壁殘膠</p>	<p>3樓 A303-3 牆壁殘膠</p>	<p>3樓 A303-4 牆壁殘膠</p>
 <p>A309-1</p>	 <p>A503-3</p>	 <p>A605-1</p>
<p>3樓 A309-1 掛鈎痕</p>	<p>5樓 A503-3 牆壁殘膠</p>	<p>6樓 A605-1 牆壁、殘膠、掛鈎</p>



5樓 A503-1 牆壁殘膠



2樓 A204-2 牆壁掉漆、殘膠、掛勾



3樓 A320 公共區域牆壁油漆剝落



4樓 A401 公共區域